CREW: 81 WORK ORDER TYPE: MODIFICATIONS		03-96033-5 ISSUE DATE 01/		ISSUE DATE 01/06/11	Pag			
Originator : HOWARD HAMILTO	ON Schedule Date			Date Completed:		Failure Code:		
Planner : ALAN DEWSNUP	Priority	: 3A						
Drawing No : 2SGA-M2063D	Clearance	: NO		Completed By :		Signature :		
Equip No/Cat: 2SGAA 2	Tag Request	:				J		
Project ID :	Text ID	:		Accepted By :		Signature :		
Shutdown : N No Shutdown	Frequency	: NOT	SCHEDULED			J		
Ref No :	Last Reading					** Delay Co	des Legend **	
	3		J		W=Whse	-	Tag TL=Tool	P=Plan
					** R	ecord Time Da		Delays
Step Job Scope		MN DY	Safety and Addit	tional Information	Emp No	Date	Hours	Code/Hrs
1 COST TRACKER FOR TEI	TO COMPLETE	1 1						
	ING, SUPPORT BEAMS AND)						
HANDRAILS.								
*********	******							
**********	******							
SCOPE:								
1- TEI TO PROVIDE MA	TERIALS AND LABOR TO							
COMPLETE SCOPE OF WO	RK AS DETAILED BY							
HOWARD HAMILTON.								
2- COST NOT TO EXCEE	52,283.28.							

						* IMPORTANT N		
							YOUR OWN SAFE'	
							PPE IS WORN	
							OU HAVE ANY Q	
							S, SAFETY COD	•
					REQUIRED PP	E, PLEASE CON	TACT YOUR SUP	ERVISOR.
Job Feedback/Historical Note	es:					B) \$E		



P7_032281

CREW: 81 WORK ORDER TYPE: MODIFICATIONS 03-96033-5 ISSUE DATE 01/06/11 Page 2 Of 2

*	**	Work	Order	Parts	List	**

	Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	DIRECT	UNIT#2 DCS REMOTE I/O CABINET MEASURING THE AIR FLOW FOR THE	R 198910	01/19/04	EA	0	0	0
2	DIRECT	UNIT #2 DCS REMOTE I/O CABINET MEASURING AIR FLOW FOR NEW AB	04-45618-1	02/06/04	EA	1	0	1
3	DIRECT	INSTALLATION OF IBAM I/O CABINET.	04-45618-1	04/26/04	EA	1	0	1

P7_032282